



LEGEND

STRUCTURAL CONDITION

	Satisfactory
	Average state
	Serious state

References:
Fig. 0.3a , Fig. 10.4

DATE:2006-07

DRAWN BY:
CRCI

N
↑

10 0 10 20 40 60 m

SCALE :- 1 : 3000

CLIENT:
Archaeological Survey of India

CCMP, RED FORT, DELHI